10/628, 197.





THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of

U.S. Patent No.

7,005,639 B2

Issued

February 28, 2006

Title

SYSTEM AND METHOD OF COMPOSITION

CORRECTION FOR BETA GAUGES

Certificate

Docket No.

ACC 048 PA

MAY 0.8 2006

of Correction

Commissioner for Patents Certificate of Correction Branch PO Box 1450 Alexandria VA 22313-1450

CERTIFICATE OF MAILING

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, Certificate of Correction Branch, PO Box 1450, Alexandria, VA 22313 on May 1, 2006.

Attorney Richard C. Stevens

Reg. No. 28,046

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION FOR PTO MISTAKE UNDER 35 U.S.C. 254 AND 37 C.F.R. 1.322

In the matter of U. S. Patent No. 7,005,639 B2, it is respectfully requested that a Certificate of Correction be issued to cover the following errors which occurred in the printing of the patent.

In the Specification:

Col. 5, line 5, "signal arrays, S20a, 3200 and" should read --signal arrays, 320a, 3200 and--;

Col. 5, line 40, " $S_T(X)$ is an array" should read -- $S_T(x)$ is an array--;

Col. 5, line 54, "signal arrays, $S_T(X)$," should read --signal arrays, $S_T(x)$ --;

Col. 7 line 21, "Wt(x) \approx SWt_T(x) \approx SWt_o(x)=SWt₁(x)" should read --Wt(x) \approx SWt_T(x)

 $\approx SWt_0(x) \approx SWt_1(x)$ --.

Patent No. US 7,005,639 B2 Page 2 May 1, 2006

REMARKS

It is respectfully requested that a Certificate of Correction be issued for the above-identified patent. All of the above errors occurred during the printing of the patent and, therefore, no fee is due. Two (2) copies of the required Certificate of Correction Form PTO/SB/44 are enclosed.

Respectfully submitted,

STEVENS & SHOWALTER, L.L.P.

Richard C. Stevens Reg. No. 28,046

7019 Corporate Way Dayton OH 45459-4238 Telephone: 937/438-6848

Facsimile: 937/438-2124

Email: rcstevens@speakeasy.net

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7.005.639 B2

DATED

: February 28, 2006

INVENTOR(S): Steven Perry Sturm

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification:

Col. 5, line 5, "signal arrays, S2oa, 32oo and" should read --signal arrays, 32oa, 32oo and--;

Col. 5, line 40, "ST(X) is an array" should read --ST(x) is an array--;

Col. 5, line 54, "signal arrays, ST(X)," should read --signal arrays, ST(x) --;

Col. 7, line 21, "Wt(x) \approx SWt_x(x) \approx SWt_x(x) = SWt_x(x)" should read --Wt(x) \approx SWt_x(x) \approx SWt_x(x) \approx SWt_x(x) \approx SWt_x(x) = SWt_x

MAILING ADDRESS OF SENDER:

Richard C. Stevens

Stevens & Showalter LLP 7019 Corporate Way

Dayton OH 45459-4238

PATENT NO.

7,005,639 B2

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7.005.639 B2

DATED

: February 28, 2006

INVENTOR(S): Steven Perry Sturm

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification:

Col. 5, line 5, "signal arrays, S2oa, 32oo and" should read --signal arrays, 32oa, 32oo and--;

Col. 5, line 40, "ST(X) is an array" should read -ST(x) is an array-;

Col. 5, line 54, "signal arrays, ST(X), " should read --signal arrays, ST(x) --;

 $Col. \ 7, \ line \ 21, \ "Wt(x) \approx SWt_r(x) \approx SWt_o(x) = SWt_1(x) " \ should \ read \ --Wt(x) \approx SWt_7(x) \approx SWt_0(x) \approx SWt_1(x) --.$

MAILING ADDRESS OF SENDER:

Richard C. Stevens

Stevens & Showalter LLP 7019 Corporate Way

Dayton OH 45459-4238

PATENT NO.

7,005,639 B2

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

History of Source